




Note:

This figure is intended to illustrate ongoing external inputs of solids and contaminants to Newtown Creek and in-creek processes that affect the redistribution of solids and contaminants in the creek.

*Lateral groundwater discharges occur in vertical permeable shoreline areas that include vertical wood, wood, precast concrete, and pile-supported concrete bulkheads.

Figure is adapted from Figures 8-1 and 8-2 in the Remedial Investigation Report, RI/FS, Newtown Creek, March 2023 prepared by Anchor QEA.

Newtown Creek Conceptual Site Model